



Connect. Accelerate. Outperform.™

# **MLNX\_EN for Linux Release Notes**

Rev 3.0-1.0.1

## NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT (“PRODUCT(S)”) AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES “AS-IS” WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER’S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies  
 350 Oakmead Parkway Suite 100  
 Sunnyvale, CA 94085  
 U.S.A.  
[www.mellanox.com](http://www.mellanox.com)  
 Tel: (408) 970-3400  
 Fax: (408) 970-3403

Mellanox Technologies, Ltd.  
 Hakidma 26  
 Ofer Industrial Park  
 Yokneam 2069200  
 Israel  
[www.mellanox.com](http://www.mellanox.com)  
 Tel: +972 (0)74 723 7200  
 Fax: +972 (0)4 959 3245

© Copyright 2015. Mellanox Technologies. All Rights Reserved.

Mellanox®, Mellanox logo, BridgeX®, ConnectX®, Connect-IB®, CoolBox®, CORE-Direct®, GPUDirect®, InfiniBridge®, InfiniHost®, InfiniScale®, Kotura®, Kotura logo, MetroX®, MLNX-OS®, PhyX®, ScalableHPC®, SwitchX®, TestX®, UFM®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

CyPU™, ExtendX™, FabricIT™, FPGADirect™, HPC-X™, Mellanox Care™, Mellanox CloudX™, Mellanox Open Ethernet™, Mellanox PeerDirect™, Mellanox Virtual Modular Switch™, MetroDX™, NVMeDirect™, StPU™, Switch-IB™, Unbreakable-Link™ are trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners.

# Table of Contents

<b>Table of Contents</b> .....	<b>1</b>
<b>List of Tables</b> .....	<b>1</b>
<b>Release Update History</b> .....	<b>2</b>
<b>Chapter 1 Introduction</b> .....	<b>3</b>
1.1 Main Features in This Release .....	3
1.2 Unsupported Functionality/Features .....	3
1.3 Supported Platforms and Operating Systems .....	4
1.4 Supported Hypervisors .....	4
1.5 Supported HCAs Firmware Versions .....	4
<b>Chapter 2 Changes in Rev 3.0-1.0.1 From Rev 2.4-1.0.0.1</b> .....	<b>6</b>
<b>Chapter 3 Known Issues</b> .....	<b>7</b>
3.1 Ethernet Known Issues .....	7
3.2 mlx5 Driver (ConnectX®-4) Known Issues .....	9
3.3 Resiliency Known Issues .....	9
3.4 Memory Consumption Known Issues .....	10
3.5 Ethernet Performance Counters Known Issues .....	10
3.6 Hardware Known Issues .....	10
3.7 Operating Systems Known Issues .....	10
3.8 SR-IOV Known Issues .....	11
3.9 Quality of Service Known Issues .....	12
3.10 Flow Steering Known Issues .....	12
3.11 Installation/Driver Start Known Issues .....	12
3.12 Performance Known Issues .....	13
<b>Chapter 4 Bug Fixes History</b> .....	<b>14</b>
<b>Chapter 5 Change Log History</b> .....	<b>17</b>

# List of Tables

Table 1:	Release Update History	2
Table 2:	MLNX_EN for Linux Rev 3.0-1.0.1 Main Features	3
Table 3:	Supported Platforms and Operating Systems	4
Table 4:	Supported HCAs Firmware Versions	4
Table 5:	Changes in v3.0-1.0.1	6
Table 6:	Ethernet Known Issues	7
Table 7:	mlx5 Driver Known Issues	9
Table 8:	Resiliency Known Issues	9
Table 9:	Memory Consumption Known Issues	10
Table 10:	Ethernet Performance Counters Known Issues	10
Table 11:	Hardware Known Issues	10
Table 12:	Operating Systems Issues	10
Table 13:	SR-IOV Issues	11
Table 14:	Quality of Service Issues	12
Table 15:	Flow Steering Issues	12
Table 16:	Installation/Driver Start Issues	12
Table 17:	Performance Known Issues	13
Table 18:	Fixed Bugs List	14
Table 19:	Change Log History	17

# Release Update History

*Table 1 - Release Update History*

Release	Date	Description
Rev 3.0-1.0.1	June 15, 2015	Initial version

# 1 Introduction

These are the release notes for Mellanox Technologies' MLNX\_EN for Linux Rev 3.0-1.0.1 driver kit for Mellanox adapter cards supporting the following uplinks to servers:

- ConnectX®-4:
  - Ethernet (Beta): 10GigE, 25GigE, 40GigE, 50GigE and 100GigE
- ConnectX®-3/ConnectX®-3 Pro:
  - Ethernet: 10GigE, 40GigE and 56GigE<sup>1</sup>
- PCI Express 2.0: 2.5 or 5.0 GT/s
- PCI Express 3.0: 8 GT/s

## 1.1 Main Features in This Release

MLNX\_EN for Linux Rev 3.0-1.0.1 provides the following new features:

**Table 2 - MLNX\_EN for Linux Rev 3.0-1.0.1 Main Features**

Feature	Description
HCA's	Added support for ConnectX®-4 Single/Dual-Port Adapter supporting up to 100Gb/s.
Ignore Frame Check Sequence (FCS) Errors	Upon receiving packets, the packets go through a checksum validation process for the FCS field. If the validation fails, the received packets are dropped. Using this feature, enables you to choose whether or not to drop the frames in case the FCS is wrong and use the FCS field for other info.
ethtool	Updated ethtool to incorporate ConnectX®-4 adapter card functionalities.

For additional information on the new features, please refer to the MLNX\_EN User Manual.

## 1.2 Unsupported Functionality/Features

The following are the unsupported functionalities/features in MLNX\_OFED Rev 3.0-1.0.1:

- pm\_qos API - Power Management
- Adaptive Interrupt Moderation Algorithm
- Virtual Guest Tagging (VGT+)

1. 56 GbE is a Mellanox propriety link speed and can be achieved while connecting a Mellanox adapter cards to Mellanox SX10XX switch series or connecting a Mellanox adapter card to another Mellanox adapter card.

## 1.3 Supported Platforms and Operating Systems

The following are the supported OSs in MLNX\_EN for Linux Rev 3.0-1.0.1:

**Table 3 - Supported Platforms and Operating Systems**

Operating System	Platform
RHEL/CentOS 6.4	x86_64/PPC64 (Power 7)
RHEL/CentOS 6.5	x86_64/PPC64 (Power 7)
RHEL/CentOS 6.6	x86_64/PPC64 (Power 7)
RHEL/CentOS 7.0	x86_64/PPC64 (Power 7)
RHEL/CentOS 7.1	x86_64/PPC64 (Power 7)/PPC64le (Power 8)/ ARM64 (ARM is at beta level)
SLES11 SP2	x86_64/PPC64 (Power 7)
SLES11 SP3	x86_64/PPC64 (Power 7)
SLES12	x86_64/PPC64le (Power 8)
OEL 6.3	x86_64
OEL 6.4	x86_64
OEL 6.5	x86_64
OEL 6.6	x86_64
Citrix XenServer Host 6.5	i686
Fedora 19	x86_64/PPC64 (Power 7)
Fedora 21	x86_64
Ubuntu 12.04	x86_64
Ubuntu 14.04	x86_64/PPC64le (Power 8)/ARM64 (ARM is at beta level)
Ubuntu 14.10	x86_64/PPC64le (Power 8)
Debian 7.6	x86_64
Debian 8.0	x86_64
kernel 3.16 <sup>a</sup> - 4.0	

a. This kernel is supported only when using the Operating Systems stated in the table above.

## 1.4 Supported Hypervisors

The following are the supported hypervisors in MLNX\_EN Rev 3.0-1.0.1:

- KVM: RedHat 6.5, 6.6, 7.0, 7.1 Ubuntu 14.04, Sles11SP3
- Xen4.2
- XenServer6.5

## 1.5 Supported HCAs Firmware Versions

MLNX\_OFED Rev 3.0-1.0.1 supports the following Mellanox network adapter cards firmware versions:

**Table 4 - Supported HCAs Firmware Versions**

HCA	Recommended Firmware Rev.	Additional Firmware Rev. Supported
ConnectX®-4	12.0100.6440	-

**Table 4 - Supported HCAs Firmware Versions**

HCA	Recommended Firmware Rev.	Additional Firmware Rev. Supported
ConnectX®-3 Pro	Rev 2.34.5000	Rev 2.33.5100
ConnectX®-3	Rev 2.34.5000	Rev 2.33.5100
ConnectX®-2	Rev 2.9.1000	Rev 2.9.1000

For official firmware versions please see:

[http://www.mellanox.com/content/pages.php?pg=firmware\\_download](http://www.mellanox.com/content/pages.php?pg=firmware_download)



## 2 Changes in Rev 3.0-1.0.1 From Rev 2.4-1.0.0.1

*Table 5 - Changes in v3.0-1.0.1*

Category	Description
HCA's	Added support for ConnectX®-4 Single/Dual-Port Adapter supporting 100Gb/s.
ethtool	Updated ethtool to incorporate ConnectX®-4 adapter card functionalities.

## 3 Known Issues

The following is a list of general limitations and known issues of the various components of this MLNX\_EN for Linux release.

### 3.1 Ethernet Known Issues

**Table 6 - Ethernet Known Issues**

Index	Description	Workaround
1.	Ethernet PV VLAN Guest transparent Tagging (VGT) is only supported in openvswitch and not in standard Linux vBridges and libvirt For more information please see : <a href="http://libvirt.org/formatnetwork.html">http://libvirt.org/formatnetwork.html</a> (Setting VLAN tag section)	-
2.	Changing the ring size on 32-bit system may result in failure due to lack of memory. Therefore, mlx4_en will not be able to vmap enough memory and the below message will be printed in dmesg: vmap allocation for size 528384 failed: use vmalloc=<size> to increase size In this case user can enlarge the vmalloc memory by adding vmalloc=<size> to grub.conf Default vmalloc setting is 128M. It is recommended to add each time 64M of memory until desired ring size can be allocated. Please note, that in case vmalloc size is too big, the OS will fail to boot, so please use caution when adding additional memory. For more info refer to: <a href="http://www.mythtv.org/wiki/Common_Problem:_vmalloc_too_small">http://www.mythtv.org/wiki/Common_Problem:_vmalloc_too_small</a>	-
3.	Kernel panic might occur during fio splice in kernels before 2.6.34-rc4.	Use kernel v2.6.34-rc4 which provides the following solution: baff42a net: Fix oops from tcp_collapse() when using splice()
4.	When creating more than 125 VLANs and SR-IOV mode is enabled, a kernel warning message will be printed indicating that the native VLAN is created but will not work with RoCE traffic.  kernel warning: mlx4_core 0000:07:00.0: vhcr command ALLOC_RES (0xf00) slave:0 in_param 0x7e in_mod=0x107, op_mod=0x1 failed with error:0, status -28	
5.	In PPC systems when QoS is enabled a harmless Kernel DMA mapping error messages might appear in kernel log (iommu related issue).	-

**Table 6 - Ethernet Known Issues (Continued)**

Index	Description	Workaround
6.	The default priority to TC mapping assigns all priorities to TC0. This configuration achieves fairness in transmission between priorities but may cause undesirable PFC behavior where pause request for priority "n" affects all other priorities.	Run: <pre>mlnx_qos -i &lt;dev&gt; -p 0,1,2,3,4,5,6,7 -s ets,ets,ets,ets,ets,ets,ets,ets,ets -t 12,13,12,13,12,13,12,13</pre> This needs to be applied every time after loading the mlx4_en driver.
7.	Transmit timeout might occur on RH6.3 as a result of lost interrupt (OS issue). In this case, the following message will be shown in dmesg: do_IRQ: 0.203 No irq handler for vector (irq -1)	-
8.	In ConnectX®-2, RoCE UD QP does not include VLAN tags in the Ethernet header	
9.	VXLAN may not be functional when configured over Linux bridge in RH7.0 or Ubuntu14.04. The issue is within the bridge modules in those kernels. In Vanilla kernels above 3.16 issues is fixed.	-
10.	In RH6.4, ping may not work over VLANs that are configured over Linux bridge when the bridge has a mlx4_en interface attached to it.	-
11.	The interfaces LRO needs to be set to "OFF" manually when there is a bond configured on Mellanox interfaces with a Bridge over that bond.	Run: <code>ethtool -K ethX lro off</code>
12.	On SLES12, the bonding interface over Mellanox Ethernet slave interfaces does not get IP address after reboot.	1. Set "STARTMODE=hotplug" in the bonding slave's ifcfg files. More details can be found in the SUSE documentations page: <a href="https://www.suse.com/documentation/sles-12/book_sle_admin/?page=/documentation/sles-12/book_sle_admin/data/sec_bond.html">https://www.suse.com/documentation/sles-12/book_sle_admin/?page=/documentation/sles-12/book_sle_admin/data/sec_bond.html</a> 2. Enable the "nanny" service to support hot-plugging: Open the "/etc/wicked/common.xml" file. Change: " <code>&lt;use-nanny&gt;&gt;false&lt;/use-nanny&gt;</code> " to " <code>&lt;use-nanny&gt;&gt;true&lt;/use-nanny&gt;</code> " 3. Run: <pre># systemctl restart wickedd.service wicked</pre>
13.	ethtool -x command does not function in SLES OS.	-
14.	Ethertype proto 0x806 not supported by ethtool.	-

## 3.2 mlx5 Driver (ConnectX®-4) Known Issues

**Table 7 - mlx5 Driver Known Issues**

Index	Description	Workaround
1.	EEH events that arrive while the mlx5 driver is loading may cause the driver to hang.	-
2.	The mlx5 driver can handle up to 5 EEH events per hour.	If more events are received, cold reboot the machine.
3.	In PPC systems, when working with ConnectX®-4 adapter card configured as Ethernet, driver load fails with BAD INPUT LENGTH. dmesg: command failed, status bad input length(0x50), syndrome 0x9074aa	-
4.	Changing the link speed is not supported in Ethernet driver when connected to a ConnectX-4 card.	-
5.	Changing the RX queues number is not supported in Ethernet driver when connected to a ConnectX-4 card.	-
6.	Error counters such as: CRC error counters, RX out range length error counter, are missing in the ConnectX-4 Ethernet driver.	-

## 3.3 Resiliency Known Issues

**Table 8 - Resiliency Known Issues**

Index	Description	Workaround
1.	Reset Flow can run on XenServer 6 only after the active user space applications running verbs are terminated.	-
2.	SR-IOV non persistent configuration (such as VGT, VST, Host assigned GUIDs, and QP0-enabled VFs) may be lost upon Reset Flow.	Reset Admin configuration post Reset Flow
3.	Upon Reset Flow or after running restart driver, Ethernet VLANs are lost.	Reset the VLANs using the <code>ifup</code> command.
4.	Restarting the driver or running <code>connectx_port_config</code> when Reset Flow is running might result in a kernel panic	-
5.	Networking configuration (e.g. VLANs, IPv6) should be statically defined in order to have them set after Reset Flow as of after restart driver.	-
6.	The qemu version (2.0) provided in box with Ubuntu 14.04 does not work properly when more than 2 VMs are run over an Ubuntu 14.04 Hypervisor.	-
7.	Attempting to attach a PF to a VM when SR-IOV is already enabled on that PF may result in a kernel panic.	-
8.	On various combinations of Hypervisor/OSes and Guest/OSes, an issue might occur when attaching/detaching VFs to a guest while that guest is up and running.	Attach/detach VFs to/from a VM only while that VM is down.

### 3.4 Memory Consumption Known Issues

**Table 9 - Memory Consumption Known Issues**

Index	Description	Workaround
1.	"Out of memory" issues may rise during drivers load depending on the values of the driver module parameters set (e.g. log_num_cq)	-

### 3.5 Ethernet Performance Counters Known Issues

**Table 10 - Ethernet Performance Counters Known Issues**

Index	Description	Workaround
1.	In a system with more than 61 VFs, the 62nd VF and onwards is assigned with the SINKQP counter, and as a result will have no statistics, and loopback prevention functionality for SINK counter.	-
2.	Since each VF tries to allocate 2 more QP counter for its RoCE traffic statistics, in a system with less than 61 VFs, if there is free resources it receives new counter otherwise receives the default counter which is shared with Ethernet. In this case RoCE statistics is not available.	-
3.	In ConnectX®-3, when we enable function-based loopback prevention for Ethernet port by default (i.e., based on the QP counter index), the dropped self-loopback packets increase the IfRxErrorFrames/Octets counters.	-

### 3.6 Hardware Known Issues

**Table 11 - Hardware Known Issues**

Index	Description	Workaround
1.	In ConnectX®-2, if the driver load succeeds, the informative message below is presented conveying the below limitations: If port type is ETH then the maximum priority for VLAN tagged is 3 mlx4_core 0000:0d:00.0: command SET_PORT (0xc) failed: in_param=0x120064000, in_mod=0x2, op_mod=0x0, fw status = 0x40	-

### 3.7 Operating Systems Known Issues

**Table 12 - Operating Systems Issues**

Index	Description	Workaround
1.	RHEL 5.X and SLES 10 SPX are currently not supported	-

## 3.8 SR-IOV Known Issues

**Table 13 - SR-IOV Issues**

Index	Description	Workaround
1.	Enabling SR-IOV requires appending the <code>intel_iommu=on</code> option to the relevant OS in file <code>/boot/grub/grub.conf/</code> . Without that SR-IOV cannot be loaded.	-
2.	When using legacy VMs with MLNX_EN 2.x hypervisor, you may need to set the <code>'enable_64b_cqe_eqe'</code> parameter to zero on the hypervisor. It should be set in the same way that other module parameters are set for <code>mlx4_core</code> at module load time. For example, add <code>"options mlx4_core enable_64b_cqe_eqe=0"</code> as a line in the file <code>/etc/modprobe.d/mlx4_core.conf</code> .	-
3.	Attaching or detaching a Virtual Function on SLES11 SP3 to a guest Virtual Machine while the <code>mlx4_core</code> driver is loaded in the Virtual Machine may cause a kernel panic in the hypervisor.	Unload the <code>mlx4_core</code> module in the hypervisor before attaching or detaching a function to or from the guest.
4.	Enabling SR-IOV requires appending the <code>"intel_iommu=on"</code> option to the relevant OS in file <code>/boot/grub/grub.conf/</code> . Without that SR-IOV cannot be loaded.	-
5.	The known PCI BDFs for all VFs in kernel command line should be specified by adding <code>xen-pciback.hide</code> For further information, please refer to <a href="http://wiki.xen.org/wiki/Xen_PCI_Passthrough">http://wiki.xen.org/wiki/Xen_PCI_Passthrough</a>	-
6.	The <code>qemu</code> version (2.0) provided in box with Ubuntu 14.04 does not work properly when more than 2 VMs are run over an Ubuntu 14.04 Hypervisor.	-
7.	Attempting to attach a PF to a VM when SR-IOV is already enabled on that PF may result in a kernel panic.	-
8.	On various combinations of Hypervisor/OSes and Guest/OSes, an issue might occur when attaching/detaching VFs to a guest while that guest is up and running.	Attach/detach VFs to/from a VM only while that VM is down.
9.	On ConnectX®-3 HCAs with firmware version 2.32.5000 and later, SR-IOV VPI mode works only with Port 1 = ETH and Port 2 = IB.	-
10.	Occasionally, the <code>lspci   grep Mellanox</code> command shows incorrect or partial information due to the current <code>pci.ids</code> file on the machine.	1. Locate the file: <code>\$locate pci.ids</code> 2. Manually update the file according to the latest version available online at: <a href="https://pci-ids.ucw.cz/v2.2/pci.ids">https://pci-ids.ucw.cz/v2.2/pci.ids</a> This file can also be downloaded.
11	SR-IOV is not supported in XenServer 6.5.	-
12	SR-IOV is not supported in AMD architecture.	-

### 3.9 Quality of Service Known Issues

**Table 14 - Quality of Service Issues**

Index	Description	Workaround
1.	QoS is not supported in XenServer, Debian 6.0 and 6.2 with uek kernel	-
2.	When QoS features are not supported by the kernel, <code>mlnx_qos</code> tool may crash.	-

### 3.10 Flow Steering Known Issues

**Table 15 - Flow Steering Issues**

Index	Description	Workaround
1.	Flow Steering is disabled by default in firmware version < 2.32.5100.	To enable it, set the parameter below as follow: <code>log_num_mgmt_entry_size</code> should set to -1
2.	IPv4 rule with source IP cannot be created in SLES 11.x OSes.	-
3.	RFS does not support UDP.	-

### 3.11 Installation/Driver Start Known Issues

**Table 16 - Installation/Driver Start Issues**

Index	Description	Workaround
1.	Driver restart fails after <code>mlnx_en</code> installation if <code>MLNX_OFED</code> was previously installed on the system.	<ol style="list-style-type: none"> <li>1. Reboot the server after <code>mlnx_en</code> installation.</li> <li>2. Answer 'n' to the following question at the end of the installation: "Do you wish to reload the driver now? (y/n) [y] " n</li> <li>3. Run <code>"apt-get remove --purge mlnx-ofed-kernel-utils"</code></li> <li>4. Reboot the server after <code>mlnx_en</code> installation.</li> </ol>
2.	Firmware update fails during <code>mlx4_en</code> standalone installation on guest machine connect to HCA in Passthrough mode.	-
3.	On Debian 7.x, the Inbox driver is loaded instead of <code>mlx4_en</code> standalone drivers	<p>Add the following lines to <code>"/etc/rc.local"</code>:</p> <ul style="list-style-type: none"> <li>• <code>/sbin/modprobe -r mlx4_fc &gt; /dev/null 2&gt;&amp;1</code></li> <li>• <code>/sbin/modprobe -r mlx4_en &gt; /dev/null 2&gt;&amp;1</code></li> <li>• <code>/sbin/modprobe -r mlx4_ib &gt; /dev/null 2&gt;&amp;1</code></li> <li>• <code>/sbin/modprobe -r mlx4_core &gt; /dev/null 2&gt;&amp;1</code></li> <li>• <code># load the new driver</code></li> <li>• <code>/sbin/modprobe mlx4_en &gt; /dev/null 2&gt;&amp;1</code></li> </ul>

**Table 16 - Installation/Driver Start Issues (Continued)**

Index	Description	Workaround
4.	mlx4_en standalone drivers are not available after installation on SLSE11 SP3 PPC64.	Run the installation with the "--disable-kmp" flag.
5.	On RHEL 7, MLNX_EN driver v2.3-1.0.0 installation fails the first time. However, the driver is installed successfully on the second attempt.	To avoid failure on the first attempt, prior to running the installation, run: make -C /usr/src/kernels/ \$(uname -r) kernelrelease

## 3.12 Performance Known Issues

**Table 17 - Performance Known Issues**

Index	Description	Workaround
1.	On machines with irqbalancer daemon turned off, the default Ethernet interrupts will be routed to a single core which may cause overload and software/hardware lockups.	Execute the following script as root: set_irq_affinity.sh <interface or Eth device> [2nd interface or Eth device]
2.	Out of the box throughput performance in Ubuntu14.04 is not optimal and may achieve results below the line rate in 40GE link speed.	For additional performance tuning, please refer to Performance Tuning Guide.
3.	UDP receiver throughput may be lower than expected, when running over mlx4_en Ethernet driver. This is caused by the adaptive interrupt moderation routine, which sets high values of interrupt coalescing, causing the driver to process large number of packets in the same interrupt, leading UDP to drop packets due to overflow in its buffers.	Disable adaptive interrupt moderation and set lower values for the interrupt coalescing manually. ethtool -C <eth>X adaptive-rx off rx-usecs 64 rx-frames 24  Values above may need tuning, depending the system, configuration and link speed.
4.	Performance degradation might occur when bonding Ethernet interfaces on Centos 6.5	-



## 4 Bug Fixes History.

**Table 18 - Fixed Bugs List**

#	Description	Discovered in Release	Fixed in Release
1.	LRO fixes and improvements for jumbo MTU.	2.3-2.0.1	2.4-1.0.0.1
2.	Fixed a crash occurred when changing the number of rings (ethtool set-channels) when interface connected to netconsole.	2.2-1.0.1	2.4-1.0.0.1
3.	Fixed ping issues with IP fragmented datagrams in MTUs 1600-1700.	2.2-1.0.1	2.4-1.0.0.1
4.	The default priority to TC mapping assigns all priorities to TC0. This configuration achieves fairness in transmission between priorities but may cause undesirable PFC behavior where pause request for priority "n" affects all other priorities.	2.3-1.0.1	2.4-1.0.0.1
5.	Fixed a crashing issue on non-SR-IOV systems related to VxLAN with dynamic port configuration.	2.3-1.0.0	2.3-2.0.1
6.	Fixed "sleeping while atomic" error occurred when the driver ran many firmware commands simultaneously.	2.3-1.0.0	2.3-2.0.1
7.	Fixed dmesg warnings: "NOHZ: local_softirq_pending 08".	2.3-1.0.0	2.3-2.0.1
8.	Fixed erratic report of hardware clock which caused bad report of PTP hardware Time Stamping.	2.3-1.0.0	2.3-2.0.1
9.	Fixed counter index allocation for VFs which enables Ethernet port statistics.	2.3-1.0.0	2.3-2.0.1
10.	Fixed kernel panic on Debian-6.0.7 which occurred when the number of TX channels was set above the default value	2.1-1.0.0	2.2-1.0.1
11.	Fixed wrong calculation of packet true-size reporting in LRO flow	2.1-1.0.0	2.2-1.0.1
12.	Fixed a crash incidence which occurred when enabling Ethernet Time-stamping and running VLAN traffic	2.0-3.0.0	2.2-1.0.1
13.	Fixed ALB bonding mode failure when enslaving Mellanox interfaces	2.0-3.0.0	2.1-1.0.0
14.	Fixed leak of mapped memory	2.0-3.0.0	2.1-1.0.0
15.	Fixed TX timeout issues	1.5.10	2.0.-3.0.0
16.	Fixed Ethtool status report for Virtual Functions	1.5.10	2.0.-3.0.0
17.	Fixed an issue of VLAN traffic over Virtual Machine in para-virtualized mode	1.5.10	2.0.-3.0.0
18.	Fixed Ethtool operation crash while interface down	1.5.10	2.0.-3.0.0
19.	Fixed driver unloading after installation. Currently, the driver is reloaded after installation	1.5.9	1.5.10
20.	Fixed an issue related to the configuration files. Configuration files are no longer modified.	1.5.9	1.5.10

**Table 18 - Fixed Bugs List**

#	Description	Discovered in Release	Fixed in Release
21.	Fixed MTU size calculation	1.5.9	1.5.10
22.	Fixed race in join/leave multicast group flow	1.5.9	1.5.10
23.	Restored RX buffer pointer in case of failure	1.5.9	1.5.10
24.	Fixed IPMI	1.5.9	1.5.10
25.	Fixed BlueFlame race	1.5.9	1.5.10
26.	Added sanity check for module parameters	1.5.9	1.5.10
27.	Fixed lost of connectivity bug for iperf long run	1.5.9	1.5.10
28.	Fixed bad TX completion notification request logic, could lead to TX timeout	1.5.8.3	1.5.9
29.	Fixed PowerPC connectivity loss	1.5.8.3	1.5.9
30.	Fixed possible transmit timeout under heavy traffic load	1.5.8.2	1.5.8.3
31.	Fixed error flows in case of MSI-X assignment failures	1.5.7.2	1.5.8.2
32.	Fixed loss of multicast traffic during addition of multicast addresses	1.5.7.2	1.5.8.2
33.	Enabled legal MTU configuration prior to interface bring-up	1.5.7.2	1.5.8.2
34.	Fixed WoL configuration behavior for single ported devices	1.5.7	1.5.7.2
35.	Fixed the assignment of valid flow control parameters during interface initialization	1.5.7	1.5.7.2
36.	Fixed qdisc behavior when transmitting packets with VLAN ID 0	1.5.7	1.5.7.2
37.	Fixed badly placed counters on ethtool -S report	1.5.7	1.5.7.2
38.	Fixed the crash occurred during initialization if an invalid mac address was burned on the card	1.5.6	1.5.7
39.	Fixed a bug where interface link state was not updated correctly in certain scenarios	1.5.6	1.5.7
40.	Fixed a crash occurred when LRO enabled via ethtool but disabled in module parameter	1.5.6	1.5.7
41.	Fixed a warning when using netconsole	1.5.6	1.5.7
42.	Fixed a crash occurred during driver initialization due to multicast list update	1.5.6	1.5.7
43.	Fixed a bug that caused the driver not to work with MSI-X on RedHat EL4 systems	1.5.1.3	1.5.6
44.	Fixed the driver functionality in case the device is enslaved to bond with VLANs over it	1.5.1.3	1.5.6
45.	Fixed the crash occurred when sending malformed TCP packets	1.5.1.3	1.5.6

**Table 18 - Fixed Bugs List**

#	Description	Discovered in Release	Fixed in Release
46.	If the two ports of a ConnectX/ConnectX-2 device are bonded together and one port is closed, then the other port will cease carrying traffic. Fixed in this release.	1.4.2	1.5.1.3
47.	Multiple error messages when working under bonding on some operating systems	1.4.2	1.5.1.3
48.	Fixed a bug avoiding the driver to work with MSI-X on RedHat EL4 systems		1.4.2
49.	Enabled the driver to load on systems with 32 cores and higher		1.4.2
50.	The driver is being stuck if the HW/FW stops responding, reset is done instead		1.4.2
51.	Fixed recovery flows from memory allocation failures		1.4.2
52.	Corrected checksum reports on SLES11 systems		1.4.2
53.	When the system is low on memory, the driver now allocates smaller RX rings		1.4.2
54.	The driver now retries to obtain MSI-X vectors if the initial request is rejected by the OS		1.4.2

## 5 Change Log History

**Table 19 - Change Log History**

Release	Category	Description
Rev 2.4-1.0.0.1	mlx4_en net-device Ethtool	Added support for Ethtool speed control and advertised link mode.
		Added ethtool txvlan control for setting ON/OFF hardware TX VLAN insertion: <code>ethtool -k txvlan [on/off]</code>
		Ethtool report on port parameters improvements.
		Ethernet TX packet rate improvements.
	Virtualization	VXLAN fixes and performance improvements.
	Ethernet net-device	New adaptive interrupt moderation scheme to improve CPU utilization.
Rev 2.3-2.0.1	Reset Flow	Added support for Enhanced Error Handling for PCI (EEH), a recovery strategy for I/O errors that occur on the PCI bus.
	VXLAN	Bug Fixes, see <a href="#">Section 4, “Bug Fixes History.”</a> , on page 14
Rev 2.3-1.0.0	Ethernet	Added support for arbitrary UDP port for VXLAN. From upstream 3.15-rc1 and onward, it is possible to use arbitrary UDP port for VXLAN. This feature requires firmware version 2.32.5100 or higher. Additionally, the following kernel configuration option <code>CONFIG_MLX4_EN_VXLAN=y</code> must be enabled.
		MLNX_EN no longer changes the OS sysctl TCP parameters.
Rev 2.2-1.0.1	Reset Flow	Reset Flow is not activated by default. It is controlled by the <code>mlx4_core'internal_err_reset'</code> module parameter.
	Ethernet	Ethernet VXLAN support for kernels 3.12.10 or higher
		Power Management Quality of Service: when the traffic is active, the Power Management QoS is enabled by disabling the CPU states for maximum performance.
		Ethernet PTP Hardware Clock support on kernels/OSes that support it
Performance	Out of the box performance improvements: <ul style="list-style-type: none"> <li>• Use of affinity hints (based on NUMA node of the device) to indicate the IRQ balancer daemon on the optimal IRQ affinity</li> <li>• Improvement in buffers allocation schema (based on the hint above)</li> <li>• Improvement in the adaptive interrupt moderation algorithm</li> </ul>	

**Table 19 - Change Log History**

Release	Category	Description
Rev 2.1-1.0.	mlx_en	Added reporting autonegotiation support
		Added Transmit Packet Steering (XPS) support
		Added reporting 56Gbit/s link speed support
		Added Receive Flow Steering (RFS) support in UDP
		Added Low Latency Socket (LLS) support
		Added check for dma_mapping errors
Rev 2.0-3.0.0	Operating Systems	Additional OS support: <ul style="list-style-type: none"> <li>• SLES11SP3</li> <li>• Fedora16, Fedora17</li> </ul>
	Hardware	Added ConnectX-3 Pro support
Rev 1.5.10	General	<a href="#">Section 4, “Bug Fixes History.”, on page 14</a>
Rev 1.5.9	Operating Systems	Added support for kernel.org 3.5
	Performance	Improved latency by optimizing RX repost mechanism
Rev 1.5.8.3	Operating Systems	Added support for RHEL6.3
Rev 1.5.8.2	Operating Systems	Added support for new kernels: 3.1, 3.2, 3.3
Rev 1.5.8.2	Performance	Moved to interrupt mode to handle TX completions
		Added IRQ affinity control scripts (please see README file for more details)
		Optimized Numa aware memory allocations
		Optimized interrupt usage for TX/RX completions
	Installation	Added KMP compliant installation process
	Linux Tools	Added support for Ethtool
Rev 1.5.7.2	Operating Systems	Added support for new OS's: <ul style="list-style-type: none"> <li>• RHEL6.2</li> <li>• RHEL5.8</li> <li>• SLES11SP2</li> </ul>
		Performance
	Performance	Added the usage of Toeplitz hash function for RSS calculation
		Reports/Statistics

**Table 19 - Change Log History**

Release	Category	Description
Rev 1.5.7	Operating Systems	Added support for new OS's: <ul style="list-style-type: none"> <li>• RHEL6.1</li> <li>• RHEL5.5</li> <li>• RHEL5.7</li> <li>• kernel.org (2.6.37, 2.6.38, 2.6.39, 3.0)</li> <li>• RHEL6.1 KVM</li> </ul>
	Performance	Improved performance on PPC systems (Using GRO where LRO is not efficient)
		Added IPv6 support to LRO
		Incremented number of TX and RX queues
		Enabled NAPI usage at any given time
		Enabled TX completions spread among multiple MSI-X vectors
		Improved small packets packet rate
		Added 40GigE support (including Ethtool report)
		Added NUMA support
		Added general performance improvements
Rev 1.5.6	Operating Systems	Added support for new OS's: <ul style="list-style-type: none"> <li>• RHEL6.0</li> <li>• RHEL5.6</li> <li>• SLES11SP1</li> <li>• kernel.org (2.6.35, 2.6.36)</li> </ul>

**Table 19 - Change Log History**

Release	Category	Description
Rev 1.5.6	Performance	Added blue flame support for kernels > 2.6.28 (improves TX latency by 0.4 usec)
		Added RX acceleration feature that supports recvmmsg and recvmmsg system calls. See MLNX_EN_Linux_README for further details.
		Added option to use interrupts for TX completion (polling is the default)
		Added option to disable NAPI (enabled by default)
		Added support for control number of RX rings from module parameter
		Added interrupt vector per each RX ring. See /proc/interrupts
		Adaptive moderation improvements
		Added system tuning option to achieve better performance (idle loop polling)
	Linux Tools	Added hardware revision report via Ethtool
	Multicast Filtering	Added exact match multicast filtering
Driver Load	Link is brought up upon driver load	
Rev 1.5.1.3	Operating Systems	Added support for new OS's: <ul style="list-style-type: none"> <li>• RHEL5.5</li> <li>• kernel.org (2.6.16 - 2.6.32)</li> </ul>
	Performance	Added UDP RSS support (on ConnectX-2 HW only)
		Improved VLAN tagging performance
	Linux Tools	Ethtool -e support